DEPARTMENT OF THE ARMY
CAMP STANLEY STORAGE ACTIVITY, MCAAP
25800 RALPH FAIR ROAD, BOERNE, TX 78015-4800

August 5, 2011

U-106-11

[redacted]
8902 Cedar Trail
Boerne, TX 78006

SUBJECT: Sampling of Water Well OFR-3, Located at 25617 Old Fredericksburg Rd.

Dear [redacted]

Camp Stanley Storage Activity (CSSA) collected a groundwater sample from your well (OFR-3) on 5/31/11. This sample was submitted to a laboratory contracted by CSSA's environmental contractor for volatile organic compound (VOC) analysis. This letter provides you with the VOC data from the laboratory results and a formal thank you for your assistance in this groundwater monitoring effort.

An abbreviated summary of analytical results compared to maximum contaminant levels (MCL) allowed in drinking water by the U.S. EPA under the Safe Drinking Water Act is provided in the table below.

Date Sampled	**VOC Compound**	**Result (ppb)**	**MCL (ppb)**
Well OFR-3, located at 25617 Old Fredericksburg Rd.			
5/31/11	Tetrachloroethene (PCE)	3.43	5
	Trichloroethene (TCE)	1.87	5
	cis-1,2-Dichloroethene (DCE)	<0.07 (non-detect)	70

Based on the analytical data, low levels of the VOCs PCE and TCE were identified in the water sample from your well before granular activated carbon (GAC) filtration. These concentrations are below the applicable MCLs and do not affect usability of your well. The concentrations reported for VOCs PCE and TCE were above the MCLs in the past. Therefore, a filtration system was installed on your well.

The filtration system was installed by Carbonair Environmental Systems of San Marcos, Texas. The system will remain in operation for the foreseeable future or until significant reductions in contamination levels are seen in the water in your well before it enters the filtration system. As we discussed at the time of installation, CSSA will continue to be responsible for all costs associated with operation and maintenance of this system. CSSA will continue to send a representative every 3 weeks to exchange the five-micron pre-and post-filters in the system.

Carbonair exchanged the first carbon canister and performed other routine maintenance on your system in July 2011. If you experience any problems with the system, please let the installer or CSSA know immediately. Carbonair is very responsive and can make additional

maintenance visits if needed. Post-GAC samples were not collected this event but are scheduled to be collected again during the September 2011 sampling event.

[illegible]