

Kathleen Hartnett White, *Chairman*
R. B. "Ralph" Marquez, *Commissioner*
Larry R. Soward, *Commissioner*
Glenn Shankle, *Executive Director*



TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

Protecting Texas by Reducing and Preventing Pollution

November 17, 2004

LTC Jason D. Shirley
Installation Manager
Camp Stanley Storage Activity
25800 Ralph Fair Road
Boerne, TX 78015-4800

Re: Final Solid Waste Management Unit (SWMU) B-23A Closure Report - Additional Information Requested;
Camp Stanley Storage Activity, Boerne, TX;
TCEQ SWR No. 69026

Dear LTC Shirley:

The Texas Commission on Environmental Quality (TCEQ) received the report entitled *Final Solid Waste Management Unit B-23A Closure Report* dated August 2004. SWMU B-23A was used as a disposal trench. The report documented the excavation and removal of 20 cubic yards of soil and surface waste. Excavation activities also indicated no buried wastes material at SWMUB-23A. Confirmation sampling for metals constituent of concern showed levels below background concentration. The report recommends closure of SWMU B-23A according to Risk Reduction Standard No. 1.

The TCEQ has completed its review of the report. Based on our review, the TCEQ cannot approve the above-mentioned report at this time. A list of comments or request for additional information is as follows:

1. Please provide additional information regarding M34.
2. Please provide information concerning the disposal of the M34 ampules.


Please prepare a written response to each request for additional information. An original and one copy of the written response to these requests must be submitted to the TCEQ at the letterhead address using mail code number MC-127. An additional copy should be submitted to the TCEQ Region 13 Office in San Antonio. Your response must be received on or before December 20, 2004. The facility name, location and identification number(s) in the TCEQ reference line above should be included in your response.

LTC Shirley
November 17, 2004
Page 2

To document compliance with the Texas Professional Geoscience Act, the Remediation Division will not review reports and documents received on or after September 1, 2004 that do not contain the seal of a Texas Professional Geoscientist for geoscience services and work. Reports and documents containing geoscience information that are not stamped with a Texas Professional Geoscience seal will be returned to the submitting party. For further information, please consult the webpage of the Texas Board of Professional Geoscience at <http://www.tbpg.state.tx.us>. Any inquiry regarding what constitute geoscience information or what information requires a Professional Geoscientist seal shall be made to the Board by calling 512.936.4400, in Austin, Texas. Examples of geology work which requires a Professional Geologist seal are provided in the link: <http://www.tnrcc.state.tx.us/permitting/remed/techsupp/PGReports.pdf>.

Please contact me at 512.239.2371 or at srayos@tceq.state.tx.us if you wish to discuss or if you have questions concerning this letter. Please use Mail Code MC-127 when responding by mail.

Sincerely,



Sonny Rayos, P.G., Project Manager
Team I, Corrective Action Section
Remediation Division
Texas Commission on Environmental Quality

cc: Mr. Greg Lyssy, U.S. EPA Region 6, 1445 Ross Ave (6SF-LT), Dallas, TX 75202-2733
Mr. Brian Murphy, Camp Stanley Storage Activity, 25800 Ralph Fair Road, Boerne, TX 78015-4800
Ms. Julie Burdey, Parsons Engineering, 8000 Centre Park Drive, Suite 200, Austin, TX 78754
Waste Program Manager, TCEQ Region 13 Office, San Antonio, TX