

IRON RICH CLAY LENS CAUSING READING.
NO SCRAP METAL FOUND IN EXCAVATION.

STORMWATER DRAINAGE
INTO CRATER

IRON RICH CLAY LENS CAUSING READING.
NO SCRAP METAL FOUND IN EXCAVATION.

ANOMALY IS A THIN
LAYER OF CLAY

ANOMALY CAUSED
BY SCRAP METAL
ON SURFACE.





FIGURE 3.10

MAGNETIC ANOMALIES
DETECTED & REMOVED
FROM CRATER 4

JUNE 1996

CAMP STANLEY STORAGE ACTIVITY

1319.5 = ELEVATION AT CENTER OF CRATER
1321.0 = ELEVATION OF CRATER EDGE