


Profile: NW-SE Line 2

Measured apparent resistivity section



Model resistivity section - 7.7% Inversion RMS error

