

Kathleen Hartnett White, *Chairman*  
R. B. "Ralph" Marquez, *Commissioner*  
Larry R. Soward, *Commissioner*  
Glenn Shankle, *Executive Director*



## TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

*Protecting Texas by Reducing and Preventing Pollution*

November 5, 2004

LTC Jason D. Shirley  
Installation Manager  
Camp Stanley Storage Activity  
25800 Ralph Fair Road  
Boerne, TX 78015-4800

Re: Final Well Installation Report - Additional Information Requested;  
Camp Stanley Storage Activity, Boerne, TX;  
TCEQ SWR No. 69026

Dear LTC Shirley:

The Texas Commission on Environmental Quality (TCEQ) has reviewed the report entitled *Final Well Installation Report Wells CS-MW11A through CS-MW19 and Westbays 01 through 04* dated August 2004. The TCEQ requests the following additional information:

1. Please provide hard copies of all well logs as presented in Appendix A;
2. Please submit State of Texas Well Log for each well; and
3. Please update and submit facility wide monitor well location maps. Individual maps should be constructed for wells screened in the Cow Creek, Lower Glen Rose, Bexar Shale, etc.

Please prepare a written response to each comment, referencing the assigned TCEQ comment number. An original and one copy of the written response to these comments must be submitted to the TCEQ at the letterhead address using mail code number MC-127. An additional copy should be submitted to the TCEQ Region 13 Office in San Antonio. Your response must be received on or before January 10, 2005. The facility name, location and identification number(s) in the TCEQ reference line above should be included in your response.


To document compliance with the Texas Professional Geoscience Act, the Remediation Division will not review reports and documents received on or after September 1, 2004 that do not contain the seal of a Texas Professional Geoscientist for geoscience services and work. Reports and documents containing geoscience information that are not stamped with a Texas Professional Geoscience seal will be returned to the submitting party. For further information, please consult the webpage of the Texas Board of Professional Geoscience at <http://www.tbpg.state.tx.us>. Any inquiry

LTC Shirley  
Page 2  
November 5, 2004

regarding what constitutes geoscience information or what information requires a Professional Geoscientist seal shall be made to the Board by calling 512.936.4400, in Austin, Texas. Examples of geology work which requires a Professional Geologist seal are provided in the link: <http://www.tnrcc.state.tx.us/permitting/remed/techsupp/PGReports.pdf>.

Please contact me at 512.239-2371 or [srayos@tceq.state.tx.us](mailto:srayos@tceq.state.tx.us) if you wish to discuss this letter.

Sincerely,



Sonny Rayos, P.G., Project Manager  
Team I, Corrective Action Section  
Remediation Division  
Texas Commission on Environmental Quality

cc: Mr. Greg Lyssy, U.S. EPA Region 6, 1445 Ross Ave (6SF-LT), Dallas, TX 75202-2733  
Mr. Brian Murphy, Camp Stanley Storage Activity, 25800 Ralph Fair Road, Boerne, TX  
78015-4800  
Ms. Julie Burdey, Parsons Engineering, 8000 Centre Park Drive, Suite 200, Austin, TX  
78754  
Waste Program Manager, TCEQ Region 13 Office, San Antonio, TX