



- A - A' Cross-Section Location
- Peizometer Locations
- VEW Locations
- VMP Locations
- Angle Boring Locations
- Monitoring Well Locations

**Figure 5.1**  
**AOC-65 Area Boring**  
**Location Map**  
**Camp Stanley Storage Activity**

**PARSONS**