

Kathleen Hartnett White, *Chairman*
R. B. "Ralph" Marquez, *Commissioner*
Larry R. Soward, *Commissioner*
Glenn Shankle, *Executive Director*



TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

Protecting Texas by Reducing and Preventing Pollution

April 11, 2005

LTC Jason D. Shirley
Installation Manager
Camp Stanley Storage Activity
25800 Ralph Fair Road
Boerne, TX 78015-4800

Re: Letter dated January 7, 2005 regarding monitor well installation reports - Approval;
Camp Stanley Storage Activity, Boerne, TX;
TCEQ SWR No. 69026;
EPA ID No. TX2210020739

Dear LTC Shirley:

The Texas Commission on Environmental Quality (TCEQ) received your letter dated January 7, 2004 which enclosed hard copies of well logs, State of Texas Well Logs and Figures 1, 2 and 3. Your letter was written in response to TCEQ request for additional information letter dated November 5, 2004. Your letter also enclosed well logs for WESTBAY Wells 1 through 4. The well logs for WESTBAY wells show the different screened intervals at different groundwater formations. The TCEQ has completed its review of the letter and enclosures and approves the enclosures as having satisfied the requested additional information as stated in TCEQ letter dated November 5, 2004.

In the TCEQ letter dated March 24, 2005, pertaining to the review of the report entitled *Final June 2004 On-Post Quarterly Groundwater Monitoring Report* dated October 2004, the TCEQ requested that future submittals from CSSA should include figures showing the locations of the WESTBAY wells with the rest of the facility monitoring wells. In addition such letter requested the submission of well logs for each of the WESTBAY wells showing and documenting the "screened" intervals. Our review of your letter dated January 7, 2005 and enclosures indicate that you have complied with these requirements of the March 24, 2005 TCEQ letter. The TCEQ apologizes for this inadvertent error.

To document compliance with the Texas Professional Geoscience Act, the Remediation Division will not review reports and documents received on or after September 1, 2004 that do not contain the seal of a Texas Professional Geoscientist for geoscience services and work. Reports and documents containing geoscience information that are not stamped with a Texas Professional

LTC Shirley
April 11, 2005
Page 2

Geoscience seal will be returned to the submitting party. For further information, please consult the webpage of the Texas Board of Professional Geoscience at <http://www.tbpg.state.tx.us>. Any inquiry regarding what constitute geoscience information or what information requires a Professional Geoscientist seal shall be made to the Board by calling 512.936.4400, in Austin, Texas. Examples of geology work which requires a Professional Geologist seal are provided in the link: <http://www.tnrcc.state.tx.us/permitting/remed/techsupp/PGReports.pdf>.

Please call me at 512.239.2371 or email me at srayos@tceq.state.tx.us if you wish to discuss or if you have questions concerning this letter. Please use Mail Code MC-127 when responding by mail.

Sincerely,



Sonny Rayos, P.G., Project Manager
Team I, Corrective Action Section
Remediation Division
Texas Commission on Environmental Quality

cc: Mr. Greg Lyssy, U.S. EPA Region 6, 1445 Ross Ave (6SF-LT), Dallas, TX 75202-2733
Mr. Brian Murphy, Camp Stanley Storage Activity, 25800 Ralph Fair Road, Boerne, TX
78015-4800
Ms. Julie Burdey, Parsons Engineering, 8000 Centre Park Drive, Suite 200, Austin, TX
78754
Waste Program Manager, TCEQ Region 13 Office, San Antonio, TX