

Kathleen Hartnett White, *Chairman*
R. B. "Ralph" Marquez, *Commissioner*
Larry R. Soward, *Commissioner*
Glenn Shankle, *Executive Director*



TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

Protecting Texas by Reducing and Preventing Pollution

November 15, 2004

LTC Jason D. Shirley
Installation Manager
Camp Stanley Storage Activity
25800 Ralph Fair Road
Boerne, TX 78015-4800

Re: Final Solid Waste Management Unit (SWMU) B- 26 Delisting Report - Approval;
Camp Stanley Storage Activity, Boerne, TX;
TCEQ SWR No. 69026

Dear LTC Shirley:

The Texas Commission on Environmental Quality (TCEQ) received the report entitled *Final Solid Waste Management Unit B- 26 Delisting Report* dated July 2004. The report concluded that although there were exceedances of site-derived CSSA background for zinc and chromium, all concentrations were below the Texas-Specific Background Concentration specified in the Texas Risk Reduction Program. In addition, based on site investigation and actual excavation, there was no evidence to indicate that waste activities were conducted at SWMU B- 26. The report recommended that SWMU B-26 be removed from the list of solid waste management units.

The TCEQ has completed its review of the report and accepts/approves the conclusion of the report that SWMU should be removed from further consideration as a solid waste management unit.


To document compliance with the Texas Professional Geoscience Act, the Remediation Division will not review reports and documents received on or after September 1, 2004 that do not contain the seal of a Texas Professional Geoscientist for geoscience services and work. Reports and documents containing geoscience information that are not stamped with a Texas Professional Geoscience seal will be returned to the submitting party. For further information, please consult the webpage of the Texas Board of Professional Geoscience at <http://www.tbpg.state.tx.us>. Any inquiry regarding what constitutes geoscience information or what information requires a Professional Geoscientist seal shall be made to the Board by calling 512.936.4400, in Austin, Texas. Examples of geology work which requires a Professional Geologist seal are provided in the link: <http://www.tnrcc.state.tx.us/permitting/remed/techsupp/PGReports.pdf>.

LTC Shirley
November 15, 2004
Page 2

Geoscientist seal shall be made to the Board by calling 512.936.4400, in Austin, Texas. Examples of geology work which requires a Professional Geologist seal are provided in the link: <http://www.tnrcc.state.tx.us/permitting/remed/techsupp/PGReports.pdf>.

Please contact me at 512.239.2371 or at srayos@tceq.state.tx.us if you wish to discuss or if you have questions concerning this letter. Please use Mail Code MC-127 when responding by mail.

Sincerely,



Sonny Rayos, P.G., Project Manager
Team I, Corrective Action Section
Remediation Division
Texas Commission on Environmental Quality

cc: Mr. Greg Lyssy, U.S. EPA Region 6, 1445 Ross Ave (6SF-LT), Dallas, TX 75202-2733
Mr. Brian Murphy, Camp Stanley Storage Activity, 25800 Ralph Fair Road, Boerne, TX 78015-4800
Ms. Julie Burdey, Parsons Engineering, 8000 Centre Park Drive, Suite 200, Austin, TX 78754
Waste Program Manager, TCEQ Region 13 Office, San Antonio, TX