



DEPARTMENT OF THE ARMY
CAMP STANLEY STORAGE ACTIVITY, RRAD
25800 RALPH FAIR ROAD, BOERNE, TX 78015-4800

9 September 2005

U-292-05

Mr. Bob Brinkman
Texas Historical Commission
History Programs Division,
P.O. Box 12276
Austin, TX 78711

Subject: Section 106 Review of Camp Stanley Storage Activity Proposed Undertaking

Dear Sir:

As required by Section 106 regulations of the National Historic Preservation Act of 1966, I am writing to inform you of several proposed undertakings of this facility, U.S. Army, Camp Stanley Storage Activity, located approximately 19 miles north of San Antonio, Texas. Specifically, we propose to renovate sections of Building 1 and to demolish Buildings 41 and 47. Photographs of these buildings are attached.

Based upon discussions at the U.S. Army, Camp Stanley Storage Activity during your visit with the engineering staff on March 16, 2005, it was unofficially agreed that these demolition/renovation activities would not have historical impact since the historical significance/relevance of these structures is questionable.

Building #1 (B-1)

B-1 serves as the installation headquarters (Figure 1, Bldg. 1). The original building was constructed in 1939, and east and west wings were added in 1983. The majority of the external work required involves these additions and as such have a limited impact on the original structure.

To refresh your memory since March, you toured in and around B-1 to assess its historical value while our facility engineer discussed the plan to update this building in an effort to comply with current applicable local and state building codes. Interior renovations will include installation of a heating, ventilating, and air conditioning (HVAC) system, electrical upgrades, plumbing upgrades, and space planning. Exterior renovations will include roof damage repairs, gutter repair/replacement, exterior lighting repairs, installation of at least one Americans with Disabilities Act (ADA) compliant entrance, and repair of exterior windows, as needed.

Exterior renovations to B-1 will include the demolition of the two attached wings. These wings will be removed due to water damage and possible structural damage caused by inadequate roof and ground drainage. New wings will be constructed that comply with current building codes.

The renovation work at B-1 will be completed in a manner to retain the original look and maintain historic conditions to the extent possible.

Building B-41

B-41, constructed in 1941, is an 800 square foot building located along Plant Road (Figure 2, Bldg. 41).

CSSA plans to demolish this building. Due to the presence of asbestos material in the building structure and the associated health hazards posed to personnel that work in and around B-41, it will be removed down to the existing concrete slab foundation.


Building B-47

B-47, constructed in 1943, is a 400 square foot building located at the intersection of Fincke Road and Central Road (Figures 3 and 4, Bldg. 47). As you may recall, you also received a tour of B-47 during the March 16 site visit and discussed the intent to demolish B-47 with our facility engineer. At the time of discussions, you indicated that you believed this type of structure was not considered eligible for the National Register of Historic Places (NRHP) due to the relative insignificant historical value.

In accordance with Section 800.6 of the Section 106 Regulation, I am requesting that the Texas Historical Commission (SHPO) review our proposal and provide approval or comment at your soonest opportunity.

If you have any questions regarding this information, please contact the Engineering Office of Camp Stanley Storage Activity at (210) 336-2372, or myself at (210) 295-7416.

Sincerely,


Jason D. Shirley
Installation Manager

Attachments: as stated

cc: Mr. Stan Citron
U.S. Army, Army Materiel Command, Command Counsel, General Law
Division (AMCCC-G)
Mr. Jim Cannizzo
U.S. Army, Army Medical Command, Fort Sam Houston, Staff Judge
Advocate
Ms. Julie Burdey
Parsons




FIG. 2






FIG 3



FIG 4