

2 LARGE (4-5" IN LENGTH)
PIECES OF SCRAP METAL


SB5

NO SUBSURFACE INDICATIONS
OF THIS ANOMALY


LOW LEVEL
ANOMALY

STORMWATER DRAINAGE
INTO CRATER

ANOMALY DUE TO METALLIC
RICH CLAY LENS. NO SCRAP
METAL FOUND DURING EXCAVATION.



LEGEND

-  SOIL MOUND
-  OR  APPROXIMATE AREA OF
MAGNETIC ANOMALY
IDENTIFIED IN NOV. 1994
-  SOIL BORING NUMBER
AND LOCATION

NOTE: CRATER 1 OCCASIONALLY CONTAINS
WATER, APPARENTLY AFTER PERIODS
OF INTENSE PRECIPITATION. THERE WAS
NO WATER IN CRATER 1 DURING THE
MAGNETOMETER SURVEY.

1331.7 = ELEVATION AT CENTER OF CRATER
1331.9 = ELEVATION OF CRATER EDGE

FIGURE 3.8

MAGNETIC ANOMALIES
DETECTED & REMOVED
FROM CRATER 1

JUNE 1996

CAMP STANLEY STORAGE ACTIVITY