

NOTE: DURING THIS INVESTIGATION, THE GROUND SURFACE WAS RESWEPT TWICE WITH THE MK26. PREVIOUSLY DETECTED ANOMALIES WERE IDENTIFIED AS BEING CAUSED BY SCATTERED SCRAP METAL AT THE SURFACE.

1325.2 ft. MSL = ELEVATION AT CENTER OF CRATER
 1327.9 ft. MSL = ELEVATION OF CRATER EDGE


LEGEND	
	SOIL MOUND
	APPROXIMATE AREA OF MAGNETIC ANOMALY IDENTIFIED IN NOV. 1994
	SOIL BORING NUMBER AND LOCATION

FIGURE 3.9

**MAGNETIC ANOMALIES
 DETECTED & REMOVED
 FROM CRATER 3**

JUNE 1996
 CAMP STANLEY STORAGE ACTIVITY