



2 LARGE (4-5" IN LENGTH)
PIECES OF SCRAP METAL




STORMWATER DRAINAGE
INTO CRATER

NO SUBSURFACE INDICATIONS
OF THIS ANOMALY

LOW LEVEL
ANOMALY

ANOMALY DUE TO METALLIC
RICH CLAY LENS. NO SCRAP
METAL FOUND DURING EXCAVATION.

LEGEND

-  SOIL MOUND
-  OR  APPROXIMATE AREA OF
MAGNETIC ANOMALY
IDENTIFIED IN NOV. 1994
-  SB5 SOIL BORING NUMBER
AND LOCATION

NOTE: CRATER 1 OCCASIONALLY CONTAINS
WATER, APPARENTLY AFTER PERIODS
OF INTENSE PRECIPITATION. THERE WAS
NO WATER IN CRATER 1 DURING THE
MAGNETOMETER SURVEY.

1331.7 = ELEVATION AT CENTER OF CRATER
1331.9 = ELEVATION OF CRATER EDGE

FIGURE 3.8

MAGNETIC ANOMALIES
DETECTED & REMOVED
FROM CRATER 1

JUNE 1996
CAMP STANLEY STORAGE ACTIVITY