

**NOTE:** DURING THIS INVESTIGATION, THE GROUND SURFACE WAS RESWEPT TWICE WITH THE MK26. PREVIOUSLY DETECTED ANOMALIES WERE IDENTIFIED AS BEING CAUSED BY SCATTERED SCRAP METAL AT THE SURFACE.

1325.2 ft. MSL = ELEVATION AT CENTER OF CRATER  
 1327.9 ft. MSL = ELEVATION OF CRATER EDGE

LEGEND


-  SOIL MOUND
-  OR  APPROXIMATE AREA OF MAGNETIC ANOMALY IDENTIFIED IN NOV. 1994
-  SB4 SOIL BORING NUMBER AND LOCATION

FIGURE 3.9

MAGNETIC ANOMALIES  
 DETECTED & REMOVED  
 FROM CRATER 3

JUNE 1996

CAMP STANLEY STORAGE ACTIVITY