


Profile: Line 360

Measured apparent resistivity section



Model resistivity section - 4.8% Inversion RMS error

