


Profile: NW-SE Line 1

Measured apparent resistivity section



Model resistivity section - 8.1% Inversion RMS error

