


Figure 3
 Well CS-16 Groundwater Elevation and Precipitation Data
 Camp Stanley Storage Activity, Texas



Note: Due to a malfunction, the Well 16 transducer data could not be downloaded during the September 2001 monitoring event.