


23. Vertical fractures in limestone core of B20-SB7 from 9 to 11 feet below ground level. Photograph taken by Michelle Town of Parsons ES on December 12, 1994



24. Removing core from inner barrel at B20-SB10. Facing northeast at north end of site. Photograph taken by Laura Brock of Parsons ES on December 13, 1994.