



Aerial Photo Date: May, 2003.



75 0 75 Feet

-  Soil Boring / Surface Sample Locations
-  Geophysical Survey Grid Outline
-  Intermittent Creek Bed
-  Soil Mound
-  Trench
-  Geophysical Anomaly

Due to different margins of error associated with the various methods utilized for data point collection, all sample locations are approximate. For more information see the 2001 amendment to the Field Sampling Plan, Vol. 1-4 of the Environmental Encyclopedia.

Figure B26-2

SWMU B-26 Site Map

Camp Stanley Storage Activity

