

APPENDIX C

EVALUATION OF DATA QUALITY OBJECTIVES ATTAINMENT

Activity	Objectives	Action	Objective Attained?	Recommendations
Objective 1: Meet TCEQ Requirements for Site Closure				
Attainment of Risk Reduction Standard Number 1: Closure/Remediation to Background				
Attainment of Risk Reduction Standard 1	Remove all hazardous and non-hazardous waste and waste residues and contaminated design and operating system components such as liners, leachate collection systems, and dikes from the unit or area of the unauthorized discharge. For remediation of media that have become contaminated by releases from a waste management unit or by other unauthorized discharge of hazardous or non-hazardous waste, the contaminated media must be removed or decontaminated to cleanup levels specified in this section (30 TAC 335.554(b) and (c)).	Demolition and excavation of the building foundation was conducted. Sampling was conducted to verify that no contamination was present beneath the foundation.	Yes.	Site closure under RRS1.

Activity	Objectives	Action	Objective Attained?	Recommendations
Attainment of Risk Reduction Standard 1	Determine compliance with RRS1 closure requirements by comparing to background as represented by results of analyses of samples taken from media that are unaffected by waste management or industrial activities. If the practical quantitation limit (PQL) is greater than background, then the PQL rather than background shall be used as the cleanup level provided that the person satisfactorily demonstrates to the executive director that lower levels of quantitation of a contaminant are not possible (30 TAC 335.554(d)).	Contaminant concentrations were compared to draft revised background levels (Parsons ES, May 2001) or RLs, which are equivalent to PQLs.	Yes. All results are in compliance with RRS1.	Site closure under RRS1.
	Attainment of cleanup levels shall be demonstrated by collection and analysis of samples from the media of concern (30 TAC 335.554(e)).	Samples were collected after the foundation demolition to show that the site achieves CSSA background levels for soils, which qualifies the site for closure under RRS1 standards.	Yes.	Site closure under RRS1.

Activity	Objectives	Action	Objective Attained?	Recommendations
Objective 2: Meet Requirements of 3008(h) Order for RFI				
RFI Workplan Requirements				
Field Sampling <i>(Detailed listing of methods and procedures are provided in project plans which are incorporated by reference).</i>	Conduct field sampling in accordance with procedures defined in the project work plan, SAP, QAPP, and HSP.	All sampling was conducted in accordance with the procedures described in the project plans.	Yes.	NA
Facility Investigation				
Characterization of Environmental Setting - Hydrogeology (B.3.A.1)	Evaluate hydrogeologic conditions at the site.	Groundwater of the Trinity Aquifer is being addressed through the Groundwater Investigation.	NA	NA
Characterization of Environmental Setting - Soils (B.3.A.2)	Characterize soils in accordance with USCS soil classification system (B.3.A.2(a)).	Soil types at the site are based on the SCS Bexar County Soil Survey (USDA, 1991) and are described in Section 1.3.1.	Yes.	NA
	Determine soil pH (B.3.A.2(e)).	The pH of each of the soil types evaluated as part of the background metals concentration study was determined through laboratory analysis. According to those analyses, the pH of Krum Complex soils is 7.87.	Yes.	NA
	Determine moisture content (B.3.A.2(g)).	The moisture content of each sample was analyzed and reported in the laboratory package.	Yes.	NA
Characterization of Environmental Setting – Surface Water and Sediment (B.3.A.3)	Characterize marshes, creeks, wetland areas, or ditches at the site.	No marshes, creeks, wetland areas, or ditches are present at the site. An intermittent creek runs approximately 500 feet north of the site. Direction of runoff flow has been evaluated in Sections 1.3.1 and 1.3.3.	Yes.	NA

Activity	Objectives	Action	Objective Attained?	Recommendations
Source Characterization (B.3.B)	Identify the source area (B.3.B.1).	A description of the potential source area is provided in Section 1.2.2.2.	Yes.	NA
	Identify the location of the unit/disposal area (B.3.B.2(a)).	The boundaries were initially marked from aerial photographs, and further confirmed by field investigations.	Yes.	NA
	Identify the type of unit/disposal area (B.3.B.2(b)).	The site is not a disposal area.	NA	NA
	Identify design features (B.3.A.2(c)).	All available information regarding the design of the disposal site is provided in Section 1.2.	Yes.	NA
	Identification of past and present operating practices, period of operation, age of unit/disposal area, and method used to close the unit/disposal area (B.3.B.2(d), (e), (f), and (h)).	All known information regarding these items is provided in Section 1.2. This information is from records review, interviews, aerial photo review, and visual observations.	Yes. To the extent possible with data available.	NA
	Determine general physical conditions of the site (B.3.B.2(g))	The general physical condition of the site was determined during the initial field investigation. This information is presented in Section 1.3.	Yes.	NA
Source Characterization (B.3.B) (continued)	Identify waste characteristics, including type of waste placed in the unit, physical and chemical characteristics of the wastes, and migration and dispersal characteristics of the waste (B.3.B.3).	The site is not a disposal area.	NA	NA

Activity	Objectives	Action	Objective Attained?	Recommendations
Contamination Characterization – Groundwater (B.3.C.1)	Characterize the vertical and horizontal extent of groundwater contamination.	Groundwater of the Trinity Aquifer is being addressed through the Groundwater Investigation.	NA	NA
Contamination Characterization – Soil (B.3.C.2)	Determine vertical and horizontal extent of contamination (B.3.C.2(a)).	Subsurface soils were collected from beneath the foundation.	Yes. Confirmation sampling was conducted after the foundation demolition. Sample results were below CSSA background levels, which allows the site to be closed under RRS1.	Site closure under RRS1.
	Describe soil properties (B.3.C.2(c)).	See “Characterization of Environmental Setting – Soils” above.	NA	NA
	Identify the direction of contaminant movement (B.3.C.2(d)).	Direction of contaminant movement was not determined as part of this investigation.	NA	NA
	Extrapolate future contaminant movement (B.3.C.2(e)).	Direction of contaminant movement was not determined as part of this investigation.	NA	NA
	Implement a soil boring investigation to determine the extent of soil contamination. Soil gas monitoring will be performed during drilling of all borings. Laboratory analysis of borings for contaminants of potential concern will be performed on soils at depths where either visual contamination is evident, or soil gas concentrations indicate contamination. All boreholes shall be properly abandoned.	A soil boring investigation was not necessary as part of the original Interim Measures scope of work. The objective of the investigation was to remove the building foundation and collect confirmation samples to verify no contamination was present at the site.	Yes. Confirmation soil samples were below CSSA background levels, allowing the site to be closed under RRS1 standards.	NA
	Prepare a map of all areas included in the investigation (B.3.C.2(i)).	Figures included in this report show all areas included in the investigation.	Yes.	NA

Activity	Objectives	Action	Objective Attained?	Recommendations
	All reporting limits should be below regulatory criteria.	RLs were approved by TCEQ on October 5, 1999. RLs are considered RRS1 standards for all analytes except metals.	Yes.	NA
	Perform all analyses in accordance with the AFCEE QAPP.	All analyses were performed in accordance with the AFCEE QAPP and approved variances.	Yes.	NA
		All data flagged with "U," "F," "M," and "J" are considered usable for site characterization purposes.	Yes.	NA
Contaminant Characterization – Sediment and Surface Water (B.3.C.3)	Conduct a surface water and sediment investigation to characterize contamination resulting from releases at the Facility.	AOC-53 is not located in the immediate vicinity of any creeks; therefore, surface water was not sampled as part of the AOC-53 investigation. Sediment samples were not collected as part of the AOC-53 investigation.	NA	NA
Potential Receptors (B.3.D).	Collect the information necessary to describe the human populations and environmental systems that are susceptible to contaminant exposure from the Facility.	Information regarding receptors is provided in the Risk Assessment Technical Approach Document (Volume 1-6) and Section 1.3.5. In addition, the Well Research Report identifies private groundwater users within 0.25-mile and public water suppliers within 0.5-mile of CSSA.	Yes.	NA