



75 0 75 Feet

- ⊕ Water Well Location
- ⊙ Strong Resistivity Anomaly
- Weak Resistivity Anomaly
- Gravity Anomaly
- Suspected Fracture
- Probable Fracture
- Suspected Fault
- Underground Power Line

Figure 2.2

AOC-65 Treatability Study
Location of Geophysical Anomalies

Camp Stanley Storage Activity