

Kathleen Hartnett White, *Chairman*
R. B. "Ralph" Marquez, *Commissioner*
Larry R. Soward, *Commissioner*
Margaret Hoffman, *Executive Director*



TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

Protecting Texas by Reducing and Preventing Pollution

May 17, 2004

LTC Jason D. Shirley
Installation Manager
Camp Stanley Storage Activity
25800 Ralph Fair Road
Boerne, TX 78015-4800

Re: Camp Stanley Storage Activity (CSSA), Boerne, TX;
TCEQ SWR No. 69026;
SWMU B-8 - Approval of report's recommendation


Dear LTC Shirley:

The Texas Commission on Environmental Quality (TCEQ) has reviewed the report entitled *Final SWMU B-8 RCRA Facility Investigation Report Addendum* dated December 2003. SWMU B-8 is located within the North Pasture area of the outer cantonment. The report recommends the removal of contaminated soils before Risk Reduction Standard (RRS) No. 1 closure can be attained. The report further recommends the service of unexploded ordnance (UXO) specialists during the removal activities because ordnance and explosives (OE) scrap and UXO have been found. In the alternative, the report recommended in-situ stabilization using Phosphate-Induced Metals Stabilization (PIMS) to achieve Tier 1 Protective Concentration Levels (PCLs) under the Texas Risk Reduction Program (TRRP) rules.

The TCEQ has completed a review of the report. The TCEQ concurs with the proposals as itemized in the report. Within 30 days of Camp Stanley's final decision on the preferred closure method (i.e., removal and disposal versus in-situ stabilization of contaminants), please provide a written notice to the TCEQ itemizing the chosen closure methodology. In addition to the notice, please provide a list of all constituents that will be used for verification/confirmation sampling. CSSA should also include a proposal to remediate or cleanup areas outside SWMU B-8 that have exceeded the cleanup values specified in RRS No. 1.

Please call me at (512) 239-2371 or email me at srayos@tceq.state.tx.us if you have questions concerning this letter. Please submit an original and one copy of all correspondence to the Corrective Action Section at Mail Code MC-127 with an additional copy submitted to the TCEQ Region 13 Office in San Antonio. The TCEQ Solid Waste Registration No. 69026 should be referenced in all submittals.

Sincerely,


Sonny Rayos, P.G., Project Manager
Team I, Corrective Action Section
Remediation Division

cc: Mr. Greg Lyssy, U.S. EPA Region 6, 1445 Ross Ave (6SF-LT), Dallas, TX 75202-2733
Ms. Julie Burdey, Parsons Engineering, 8000 Centre Park Drive, Suite 200, Austin, TX 78754
Waste Program Manager, TCEQ Region 13 Office, San Antonio, TX

P.O. Box 13087 • Austin, Texas 78711-3087 • 512/239-1000 • Internet address: www.tceq.state.tx.us