

Bryan W. Shaw, Ph.D., P.E., *Chairman*  
Toby Baker, *Commissioner*  
Zak Covar, *Commissioner*  
Richard A. Hyde, P.E., *Executive Director*



## TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

*Protecting Texas by Reducing and Preventing Pollution*

November 12, 2014

Mr. Jason Shirley  
Installation Manager  
Camp Stanley Storage Activity  
25800 Ralph Fair Road  
Boerne, TX 78015

Re: Approval with Comments  
*RCRA Facility Investigation (RFI) Report*, dated August 2014  
*Corrective Measures Study (CMS) Report*, dated October 2014  
TCEQ SWR No. 69026; CN602728206; RN100662840  
EPA ID No. TX2210020739

Dear Mr. Shirley:

The Texas Commission on Environmental Quality (TCEQ) has reviewed the above-referenced reports that were submitted in accordance with the Resource Conservation and Recovery Act (RCRA) Section 3008(h) Administrative Order on Consent for Camp Stanley Storage Activity (CSSA), Docket No. RCRA-VI 002(h)-H FY99, dated May 5, 1999. The purpose of the RFI Report was to characterize the environmental setting, source of contamination, degree, and extent of contamination, and actual or potential receptors. The purpose of the CMS Report was to screen and develop corrective measures alternatives for removal, containment, treatment, and/or remediation of the contamination that has been identified at CSSA as described in the RFI Report.

Based on the information provided, the TCEQ approves the RFI Report and CMS Report with the following comments.

- Please include the Maximum Contaminant Levels (MCLs) and/or action levels for the site contaminants of concern in Table 3.1 of the RFI Report.
- In the RFI Report, the legend for Figure 3.3 *DCE Concentrations for LGR Wells, September 2013* labels 10 µg/L as the MCL for cis-1,2-DCE. This appears to be a mistake as 70 µg/L is described in the report as being the MCL for cis-1,2-DCE. Please revise the legend, review the map for accuracy, and make any other applicable changes to Figure 3.3.

Mr. Shirley  
Page 2  
November 12, 2014  
TCEQ SWR No. 69026

Questions concerning this letter should be directed to me at (512) 239-6526. Thank you for your continued cooperation.

Sincerely,



Amanda Pirani, Project Manager  
Team 1, VCP-CA Section  
Remediation Division  
Texas Commission on Environmental Quality

ALP/mdh

cc: Mr. Gabriel Moreno-Fergusson, CSSA, 25800 Ralph Fair Road, Boerne, TX  
78015

Ms. Julie Burdey, Parsons, Julie.Burdey@parson.com

Mr. Greg Lyssy, U.S. EPA Region 6, Mail Code 6PD-F, 1445 Ross Avenue, Dallas,  
TX 75202

Mr. Cameron Lopez, Waste Section Manager, TCEQ Region 13 Office, San  
Antonio