




3. View of B-20 site facing northeast from south side of site. Five soil mounds are on left side of photograph. Photograph taken by Jim Kerr of UXB International on November 8, 1994.



4. UXB International and Parsons ES personnel conducting prescreening for UXO at B-20 site. Photograph taken by Jim Kerr of UXB International on November 9, 1994.