



**Photograph 1. East Trench—Drums removed from trench.**



**Photograph 2. East Trench—Overexcavated eastern sidewall showing staining.**



**Photograph 3. East Trench—Overexcavated western sidewall (looking west).**



**Photograph 4. East Trench—Overexcavation of southern end of trench (looking south).**



**Photograph 5. East trench—Overexcavated section of east sidewall (looking east).**



**Photograph 6. East Trench—Overexcavation of northern end of trench (looking north).**



**Photograph 7. East Trench—Partially backfilled southwestern leg of trench (looking south).**



**Photograph 8. West Trench—East-west exploratory trench.**



**Photograph 9. West Trench—East-west exploratory trench.**



**Photograph 10. West Trench—Sidewall of Sub-trench A.**



**Photograph 11. West Trench—Sidewall of Sub-trench A.**