



Photo 1. Excavation activities at AOC-65, facing south.



Photo 2. Drainage ditch excavation at AOC-65, facing north.



Photo 3. Excavation activities at AOC-65, facing south.



Photo 4. Excavation activities at AOC-65, facing north.



Photo 5. Drainage system improvements on the east side of Building 90, facing north.



Photo 6. Drainage system improvements on the north side of Building 90, facing west.



Photo 7. Drainage system improvements on the west side of Building 90, facing north.