



DEPARTMENT OF THE ARMY
CAMP STANLEY STORAGE ACTIVITY, RRAD
25800 RALPH FAIR ROAD, BOERNE, TX 78015-4800

December 11, 2008

U-040-09

RE: Sampling of Water Well JW-29,
Located at 7830 Covey Roost

Camp Stanley Storage Activity (CSSA) collected groundwater samples from your well (JW-29) on 9/4/08. These samples were submitted to a laboratory contracted by CSSA's environmental contractor for volatile organic compound (VOC) analysis. This letter provides you with the VOC data from the laboratory results and a formal thank you for your assistance in this groundwater monitoring effort.

An abbreviated summary of analytical results compared to maximum contaminant levels (MCLs) allowed in drinking water by the U.S. EPA under the Safe Drinking Water Act is provided below:

| Date Sampled | VOC Compound | Result (ppb) | MCL (ppb) |
|---|--------------------------------------|--------------------|-----------|
| Well JW-29, Located at 7830 Covey Roost | | | |
| 9/4/08 | Tetrachloroethene (PCE) | 0.13F | 5 |
| | Trichloroethene (TCE) | <0.05 (non-detect) | 5 |
| | <i>cis</i> -1,2-Dichloroethene (DCE) | <0.07 (non-detect) | 70 |

*The "F" qualifier indicates the value is above the laboratory method detection limit, but below the laboratory reporting limit for the compound.

Based on the analytical data, low levels of the VOC PCE were identified in water samples from your well. These levels are below the applicable MCL and do not affect usability of your well. Results from the laboratory analysis are provided as an attachment for the event included in the summary table above.

As part of the ongoing CSSA environmental program, we are continuing to investigate and cleanup VOC source areas on the installation and to track these compounds in groundwater on- and off-post. As part of this effort, we may contact you in the future to schedule another sampling event for the well listed above.

Again, we would like to thank you for your cooperation. We remain committed to making sure your water is safe to use and keeping you informed. If you have any

questions concerning this letter, please contact Glare Sanchez, Environmental Program Manager, at (210) 698-5208.

Sincerely,



Jason D. Shirley
Installation Manager

Attachments

cc: Mr. Greg Lyssy, EPA Region 6
Mr. Sonny Rayos, TCEQ Central Office
Mr. Henry Karnei, TCEQ Region 13
Ms. Kyle Cunningham, San Antonio Metropolitan Health Dist.
Ms. Julie Burdey, Parsons
Ms. Samantha Elliott, Parsons

AFCEE
ORGANIC ANALYSES DATA SHEET 2
RESULTS

Analytical Method: EPA 8260B Preparatory Method: 5030B AAB #: 080912AH-125868
 Lab Name: APPL, Inc Contract #: W91278-06-D-0026/DY02
 Field Sample ID: JW-29 Lab Sample ID: AX83433 Matrix: Water
 % Solids: NA Initial Calibration ID: H080911
 Date Received: 05-Sep-08 Date Prepared: 12-Sep-08 Date Analyzed: 12-Sep-08
 Concentration Units: ug/L

| Analyte | MDL | RL | Concentration | Dilution | Confirm | Qualifier |
|-------------------|------|-----|---------------|----------|---------|-----------|
| 1,1-DCE | 0.12 | 1.2 | 0.12 | 1 | | U |
| Cis-1,2-DCE | 0.07 | 1.2 | 0.07 | 1 | | U |
| TCE | 0.05 | 1.0 | 0.05 | 1 | | U |
| Tetrachloroethene | 0.06 | 1.4 | 0.13 | 1 | | F |
| Trans-1,2-DCE | 0.08 | 0.6 | 0.08 | 1 | | U |
| Vinyl chloride | 0.08 | 1.1 | 0.08 | 1 | | U |

| Surrogate | Recovery | Control Limits | Qualifier |
|-------------------------|----------|----------------|-----------|
| 1,2-DCA-D4(S) | 108 | 69-139 | |
| 4-Bromofluorobenzene(S) | 105 | 75-125 | |
| Dibromofluoromethane(S) | 101 | 75-125 | |
| Toluene-D8(S) | 105 | 75-125 | |

| Internal Std | Qualifier |
|---------------------------|-----------|
| 1,4-Dichlorobenzene-D(IS) | |
| Chlorobenzene-D5(IS) | |
| Fluorobenzene(IS) | |

Comments:

ARF: 56915