

Kathleen Hartnett White, *Chairman*
R. B. "Ralph" Marquez, *Commissioner*
Larry R. Soward, *Commissioner*
Glenn Shankle, *Executive Director*



TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

Protecting Texas by Reducing and Preventing Pollution

November 16, 2004

LTC Jason D. Shirley
Installation Manager
Camp Stanley Storage Activity
25800 Ralph Fair Road
Boerne, TX 78015-4800

Re: Final Solid Waste Management Unit (SWMU) B-33 Closure Report - Approval;
Camp Stanley Storage Activity, Boerne, TX;
TCEQ SWR No. 69026

Dear LTC Shirley:

The Texas Commission on Environmental Quality (TCEQ) received the report entitled *Final Solid Waste Management Unit B-33 Closure Report* dated July 2004. SWMU B-33 consists of contaminated foundation support for a 325 foot section of water pipe that supplies water to Building 45. According to an earlier site investigation, contaminated sand containing projectiles from Building 90 weapons testing operations was used as the foundation support for the water pipe. Laboratory analytical reports indicate the removal of contaminated foundation soils and the attainment of metals concentration that are below background levels.


The TCEQ has completed its review of the report and accepts/approves the conclusion of the report. Cleanup at SWMU B-33 attained Risk Reduction Standard No. 1 for the soils medium.

To document compliance with the Texas Professional Geoscience Act, the Remediation Division will not review reports and documents received on or after September 1, 2004 that do not contain the seal of a Texas Professional Geoscientist for geoscience services and work. Reports and documents containing geoscience information that are not stamped with a Texas Professional Geoscience seal will be returned to the submitting party. For further information, please consult the webpage of the Texas Board of Professional Geoscience at <http://www.tbpg.state.tx.us>. Any inquiry regarding what constitute geoscience information or what information requires a Professional Geoscientist seal shall be made to the Board by calling 512.936.4400, in Austin, Texas. Examples of geology work which requires a Professional Geologist seal are provided in the link: <http://www.tnrcc.state.tx.us/permitting/remed/techsupp/PGReports.pdf>.

LTC Shirley
November 16, 2004
Page 2

Please contact me at 512.239.2371 or at srayos@tceq.state.tx.us if you wish to discuss or if you have questions concerning this letter. Please use Mail Code MC-127 when responding by mail.

Sincerely,



Sonny Rayos, P.G., Project Manager
Team I, Corrective Action Section
Remediation Division
Texas Commission on Environmental Quality

cc: Mr. Greg Lyssy, U.S. EPA Region 6, 1445 Ross Ave (6SF-LT), Dallas, TX 75202-2733
Mr. Brian Murphy, Camp Stanley Storage Activity, 25800 Ralph Fair Road, Boerne, TX
78015-4800
Ms. Julie Burdey, Parsons Engineering, 8000 Centre Park Drive, Suite 200, Austin, TX
78754
Waste Program Manager, TCEQ Region 13 Office, San Antonio, TX