

**Attachment 2**

Summary of Solid Waste Management Units  
and Area of Concern Status Table

Unit No.	Description	Investigation Report(s)	Recommendations	Requested Action				Closure Approved by Regulators	Closure Type Received
				RRS1	NFA	Delisting	TRRP		
B-1	Powder and ammo burn area (1954).	RFI/Closure Report July 2002	RRS1 Closure	X				November-02	RRS1
B-2	Small arms ammunition burning area (1954)	RFI Report March 2005	RRS1 Closure	X					
B-3	Landfill area (garbage disposal and burning trash); filled in 1990-91.	RFI Report March 2005	Removal of contaminated soil						
B-4	Classified burn area (documents and trash).	RFI Report June 2002	trench and confirmation sampling						
B-5	Possible fired small arms ammo brass area. Not located.	RFI/Closure Report July 2002	RRS1 Closure	X				October-02	RRS1
B-6	Possible solid waste disposal area.	RFI/Closure Report July 2002	RRS1 Closure	X				October-02	RRS1
B-7	Possible fired small arms ammunition brass disposal area	RFI/Closure Report July 2002	RRS1 Closure	X				October-02	RRS1
B-8	Fired small arms ammo brass disposal area (piles of fire bricks, ammo shells)	RFI Report December 2003	stockpiled and in-situ soils						
B-9	Miscellaneous solid waste (metal and weapons) disposal area.	RFI/Closure Report September 2002	RRS1 Closure	X				March-03	RRS1
B-10	Ammunition disposal area.	RFI/Closure Report May 2003	RRS1 Closure	X				January-04	RRS1
B-11	Miscellaneous solid waste disposal (ammo, scrap metal, const. debris).	RFI Closure Report June 04	RRS1 Closure	X				September-04	RRS1
B-12	Landfill, WPA trash when igloos were being built	RFI Report April-05	RRS1 Closure	X				July-05	RRS1
B-13	Trash dump area.	RFI Report June 2002	Excavation of waste and surface sampling.						
B-14	Possible fired brass area - not located.	Delisting Requested June 1997	Delisting			X			
B-15/16	Landfill (target vehicles, weapons mounts)	RFI Report October 2002	Removal of debris and sampling						
B-19	Solid waste disposal area (metals and weapons).	RFI/Closure Report June 2002	RRS1 Closure	X				September-02	RRS1
B-20	Former OB/OD area	RFI Report July 2002	Remediation of stockpiled and in-situ soils						
B-21	Ammunition disposal areas	Combined with B-20							
B-22	Burn area (artillery shells).	RFI/Closure Report August 2002	RRS1 Closure	X				December-02	RRS1
B-23	Disposal trenches (two green canisters)	RFI Report April 2005	RRS1 Closure	X				July-05	RRS1
B-23A	Disposal Trench (glass ampoules of liquid)	RFI Closure Report September 2004	RRS1 Closure	X				March-05	RRS1
B-24	Spent ammo/rockets area	RFI Report May 2002	Remediation of stockpiled and in-situ soils						
B-25	Possible disposal trench	RFI Report April 2005	RRS1 Closure	X				July-05	RRS1
B-26	Possible disposal trench	Delisting Report August 2004	Delisting			X		November-04	Delisting
B-27	Sanitary landfill, consisting of 5-6 trenches (6 ft deep, 3 ft wide).	RFI Report July 2002	Removal of waste and confirmation sampling						
B-28	Disposal trenches (molten metal, ammo, ammo parts)	RFI Report April 2002	Remediation of stockpile soils						
B-29	Solid waste disposal area (in old quarry)	RFI Report April 2005	RRS1 closure	X					
B-30	Solid waste disposal area	RFI Report September 2004	RRS1 Closure	X				February-05	RRS1
B-31	Lead shot/sand pipe bedding	RFI/Closure Report July 2002	RRS1 Closure	X				November-02	RRS1
B-32	Lead shot/sand pipe bedding	RFI/Closure Report January 2003	RRS1 Closure	X				November-03	RRS1
B-33	Lead shot/sand pipe bedding	RFI Report September 2004	RRS1 Closure	X				November-04	RRS1

**Attachment 2**

Summary of Solid Waste Management Units  
and Area of Concern Status Table

Unit No.	Description	Investigation Report(s)	Recommendations	Requested Action				Closure Approved by Regulators	Closure Type Received
				RRS1	NFA	Delisting	TRRP		
B-34	Maintenance pit floor drain and discharge point	RFI Report August 2002	Delineate contamination, disposal of soil				X		
B-71	Livestock area. Inner cantonment, SW of Well 16.	--	--	(Not available)					
Bldg 40	less-than 90-day accumulation container storage area	RFI/Closure Report September 2003	RRS1 Closure	X				January-04	RRS1
Bldg 43	Inactive makeshift ammo demolition facility	RFI Report April 2005	RRS1 Closure	X					
DD	Dud ammunition disposal area	RFI Report January 2005	RRS1 Closure	X				April-05	RRS1
F-14	Hazardous waste storage area (<90-day)	RFI/Closure Report, 1995	RRS1 Closure	X				November-95	RRS1
I-1	Inactive incinerator (built in 1943), currently used for transformer storage	RFI Report February 2003	(Additional work)						
O-1	Waste liquid/sludge oxidation pond (1975)	RFI/Closure Report October 2000	RRS1 Closure	X				April-02	RRS1
Coal Bins	Coal bins (no longer in use)	Delisting Requested January 2003	Delisting			X			
AOC 35	Area immediately around Well 16. Northeast area of inner cantonment.	RFI/Closure Report October 2002	RRS1 Closure	X				February-03	RRS1
AOC 36	Area between Well 16 and B-3. Possible waste verified not present by magnetometer survey.	RFI/Closure Report April 2002	RRS1 Closure	X				August-02	RRS1
AOC 37	Livestock area. NW of Well 16 and N of Well D.	RFI/Closure Report June 2004	RRS1 Closure	X				January-05	NFA
AOC 38	Livestock area. Inner cantonment, SW of Well 16.	RFI Report September 2004	RRS1 Closure	X				February-05	RRS1
AOC 39	None. Area west of Well 16 between North Outer Rd and cantonment fence.	RFI/Closure Report April 2002	RRS1 Closure	X				September-02	RRS1
AOC 40	None. Area east of Well 16 between North Outer Rd and cantonment fence.	RFI/Closure Report May 2002	RRS1 Closure	X				August-02	RRS1
AOC 41	Gate area east of well 16. North Pasture, north of gate 6.	Report April 2005	No Further Action		X			July-05	NFA
AOC 42	None. South of SWMUs B-28 and B-19, west of B-4.	RFI Report October 2002	Excavation and sampling.						
AOC 43	Shallow trench without mounds. Metal, UXO. Located 50 ft south of B-7.	RFI/Closure Report October 2002	RRS1 Closure	X				February-03	RRS1
AOC 44	Fox holes and trenches south of B-9 along west slope of hill. UXO includes Stokes mortars and 20-lb bombs.	Delisting Report April 2005	Delisting			X		July-05	Delisting
AOC 45	Flat area with spent and undamaged bullets. Located east of B-31, near bend in road.	--	--						
AOC 46	Bermed area with stockpile of lead shot and sand. Located south of Engineering on east side of Thompkins Road.	RFI/Closure Report April 2005	--	X				July-05	RRS1
AOC 47	Area of trenches and mounds (similar to B-15/16). South of B-15/16, in SW area of East Pasture.	RFI/Closure Report June 2002	RRS1 Closure	X				September-02	RRS1
AOC 48	Three N-S trending mounds and a construction debris pile. Located north of B-15/16.	Delisting Report August 2004	Delisting Report			X		November-04	Delisting
AOC 49	Trench (4 x 7 ft) without surficial debris. Located SW of deer stand 41 in central East Pasture.	Delisting Report April 2005	Delisting			X		July-05	Delisting
AOC 50	Area with orange discolored material (most likely nickel penetrate) at ground surface. South of B-30 along gravel road.	RFI/Closure Report January 2005	RRS1 Closure	X				April-05	RRS1
AOC 51	East pasture, east of active range, approximately 25 acres, area around B-9	--	--						
AOC 52	Area west of B-4 towards Salado Creek near trees, two trenches	--	--						
AOC 53	Building foundation near B-27 at Central Road and road to "D" Tank, batteries at rear of slab	RFI/Closure Report April 2005	--	X				July-05	RRS1
AOC 54	Area near gutting pit, east of Welding Shop Building, right side of road batteries were stored in the area	Closure Report July 2004	--	X				November-04	RRS1

**Attachment 2**

Summary of Solid Waste Management Units  
and Area of Concern Status Table

Unit No.	Description	Investigation Report(s)	Recommendations	Requested Action				Closure Approved by Regulators	Closure Type Received
				RRS1	NFA	Delisting	TRRP		
AOE 55	Landfill, south of Tenberg Drive, east of Salado Creek	RFI/Closure Report Feb 04	RRS1 Closure	X					
AOE 56	Landfill, at intersection of Bernard Road and East Outer Road, surface depression on south side of intersection	Closure Report June 04	RRS1 Closure	X				September-04	RRS1
AOE 57	East of Building 98 and KOA Area, cleaning/maintenance activities performed at temporary structures	--	--						
AOE 58	Suspected disposal trench within Inner Cantonment	RFI Report October 2002	Investigate anomaly						
AOE 59	Trench-type anomaly located west Test Pad in the East Pasture	--	--						
AOE 60	Trench located west of tunnel and entrance roadway in the East Pasture.	Delisting Report April 2005	Delisting			X		July-05	Delisting
AOE 61	Suspected landfill	RFI/Closure Report October 2002	RRS1 Closure	X				February-03	RRS1
AOE 62	Located west of monitoring well MW-2 and east of Salado Creek.	--	--						
AOE 63	Area consisting of 3 barrels containing rocks, south of deer stand 41 in the East Pasture.	--	--						
AOE 64	Area east of SWMU B-4; flares observed in the area	--	--						
AOE 65	A concrete pit area that housed a metal vat that contained TCE and PCE.	RFI Report August 2003	Additional investigation, remediation ongoing						
AOE 66	Area north of Well 16 in the outer cantonment.	Closure Report June 04	RRS1 Closure	X				February-05	NFA
AOE 67	Concrete pad near Building 90 housed a vat containing cleaning solvents.	RFI Report August 2002	--						
AOE 68	Area includes metal slag/debris storage area from Wheelabrator operations next to Building 90-2.	--	--						
AOE 69	Located on west side of CSSA.	--	--	(Not available)					
AOE 70	Building used to mix pesticides. Near Building 1.	--	--	(Not available)					
AOE 72	Area containing concrete, possible asbestos. Located east of Building 94, in SW CSSA.	--	--	(Not available)					
AOE 73	Ranch landfill with overgrown trenches. Near Well 11, in northwest corner of CSSA.	--	--	(Not available)					