TATES OF

DEPARTMENT OF THE ARMY CAMP STANLEY STORAGE ACTIVITY, MCAAP 25800 RALPH FAIR ROAD, BOERNE, TX 78015-4800

March 27, 2006

U-0.55-06

Mr. 25690 IH-10 West Boerne, TX 78006

Subject: Sampling of Water Well I10-4, Located at 25690 IH-10 West

Dear

Camp Stanley Storage Activity (CSSA) collected groundwater samples from the well listed above (I10-4) on 12/19/05. These samples were submitted to a laboratory contracted by CSSA's environmental contractor for volatile organic compound (VOC) analysis. This letter provides you with the VOC data from the laboratory results and a formal thank you for your assistance in this groundwater monitoring effort. A separate letter was sent to

An abbreviated summary of analytical results compared to maximum contaminant levels (MCLs) allowed in drinking water by the U.S. EPA under the Safe Drinking Water Act is provided below:

Date Sampled	VOC Compound	Result (ppb)	MCL (ppb)
Well I10-4	, Located at 25690 IH-10 West	re Entered to the Control of the Con	
12/19/05	Tetrachloroethene (PCE)	<0.06 (non-detect)	5
	Trichloroethene (TCE)	<0.05 (non-detect)	5
	cis-1,2-Dichloroethene (DCE)	<0.07 (non-detect)	70

*The "F" qualifier indicates the value is above the laboratory method detection limit, but below the laboratory reporting limit for the compound.

Based on the analytical data, no VOCs related to CSSA's groundwater investigation were identified in water samples from your well. Results from the laboratory analysis are provided as an attachment for the above sampling event.

As part of the ongoing CSSA environmental program, we are continuing to investigate and cleanup VOC source areas on the installation and to track these compounds in groundwater on- and offpost. As part of this effort, we may contact you in the future to schedule another sampling event for the well listed above.

Again, we would like to thank you for your cooperation. We regret that your well has been impacted, but remain committed to making sure your water is safe to use and keeping you informed. If you have any questions concerning this letter, please contact Glare Sanchez, Environmental Program Manager, at 698-5208.

Sincerely,

Jason D. Shirley

Installation Manager

Attachments

cc: Mr. Greg Lyssy, EPA Region 6

Mr. Sonny Rayos, TCEQ Central Office

Mr. Henry Karnei, TCEQ Region 13

Ms. Kyle Cunningham, San Antonio Metropolitan Health Dist.

Ms. Julie Burdey, Parsons

Ms. Kimberly Vaughn, Parsons

AFCEE ORGANIC ANALYSES DATA SHEET 2 RESULTS

Analytical Method: EPA 8260B

Preparatory Method:

5030B

AAB #: 051231B-95090

Lab Name: APPL, Inc

Contract #: F41624-03-D-8613, TO 08

Field Sample ID: I10-4

Lab Sample ID: AX32865

Matrix: Water

% Solids: NA

Initial Calibration ID: M051231

Date Received: 21-Dec-05

Date Prepared: 01-Jan-06

Date Analyzed: 01-Jan-06

Concentration Units: ug/L

Analyte	MDL	\mathbf{RL}	Concentration	Dilution	Confirm	Qualifier
1,1-DCE	0.12	1.2	0.12	1		บ
Bromodichloromethane	0.06	0.8	0.06	. 1		υ
Bromoform	0.13	1.2	0.13			U
Chloroform	0.06	0.3	0.06	1	•	U
Cis-1,2-DCE	0.07	1.2	0.07	1	-	U
Dibromochloromethane	0.06	0.5	0.06	1		U
Dichlorodifluoromethane	0.11	1.0	0.11	1		U
Methylene chloride	0.51	2.0	0.51	1		U
Naphthalene	0.07	0.4	0.07	1		U
TCE	0.05	1.0	0.05	1		υ
Tetrachloroethene	0.06	1.4	0.06	.1		U
Toluene	0.06	1.1	0.06	1		υ
Trans-1,2-DCE	0.08	0.6	0.08	1		U
Vinyl chloride	0.08	1.1	0.08	1		Ü

Surrogate	Recovery	Control Limits	Qualifier	
1,2-DCA-D4(S)	101	69-139		
4-Bromofluorobenzene(S)	96.4	75-125		
Dibromofluoromethane(S)	101	75-125		
Toluene-D8(S)	99.8	75-125		

Internal Std	Qualifier
1,4-Dichlorobenzene-D(IS)	
Chlorobenzene-D5(IS)	
Fluorobenzene(IS)	

Comments:

ARF: 49399