

DEPARTMENT OF THE ARMY CAMP STANLEY STORAGE ACTIVITY, MCAAP 25800 RALPH FAIR ROAD, BOERNE, TX 78015-4800

November 1, 2011

U-145-11

8902 Cedar Trail Boerne, TX 78006

SUBJECT: Sampling of Water Well OFR-3, Located at 25617 Old Fredericksburg Rd.

Dear

Camp Stanley Storage Activity (CSSA) collected a groundwater sample from your well (OFR-3) on 9/6/11. This sample was submitted to a laboratory contracted by CSSA's environmental contractor for volatile organic compound (VOC) analysis. This letter provides you with the VOC data from the laboratory results and a formal thank you for your assistance in this groundwater monitoring effort.

An abbreviated summary of analytical results compared to maximum contaminant levels (MCL) allowed in drinking water by the U.S. EPA under the Safe Drinking Water Act is provided in the table below.

Date Sampled	VOC Compound	Result (ppb)	MCL (ppb)		
Well OFR-3,	located at 25617 Old Fredericksburg Rd	·•			
9/6/11	Tetrachloroethene (PCE)	7.72	5		
	Trichloroethene (TCE)	5.14	5		
	<i>cis</i> -1,2-Dichloroethene (DCE)	<0.07 (non-detect)	70		

Based on the analytical data, VOCs PCE and TCE were identified in the water sample from your well before granular activated carbon (GAC) filtration. The concentrations reported for VOCs PCE and TCE are currently above the MCLs and were above the MCLs in the past. Therefore, a filtration system was installed on your well.

The filtration system was installed by Carbonair Environmental Systems of San Marcos, Texas. The system will remain in operation for the foreseeable future or until significant reductions in contamination levels are seen in the water in your well before it enters the filtration system. CSSA will continue to be responsible for all costs associated with operation and maintenance of this system. CSSA will continue to send a representative every 3 weeks to exchange the five-micron pre-and post-filters in the system.

Carbonair exchanged the first carbon canister and performed other routine maintenance on your system in July 2011. If you experience any problems with the system, please let the installer or CSSA know immediately. Carbonair is very responsive and can make additional maintenance visits if needed.

On 9/6/11, CSSA collected a sample from your well (OFR-3) after the water was processed through the GAC filter system. This sample is representative of the water being delivered to your business for daily use. Based on the analytical data, no VOCs related to CSSA's groundwater investigation were identified in the sample after the second carbon canister (A2). A summary of the post-GAC analytical results is provided below. Copies of the laboratory data sheets are attached. CSSA will collect additional confirmation samples on a 6-month basis to confirm the system remains effective.

Date Sampled	VOC compound	Result (ppb)	MCL (ppb)		
Well OFR-3-A2	2, located at 25617 Old Fredericks	sburg Rd.			
9/6/11	PCE	PCE <0.06 (non-detect)			
-	TCE	<0.05 (non-detect)	5		
	cis-1,2-DCE	<0.07 (non-detect)	70		

As part of the ongoing CSSA environmental program, we are continuing to investigate and cleanup VOC source areas on the installation and to track these compounds in groundwater onand off-post. As part of this effort, your well is scheduled to be sampled again in December 2011.

Again, we would like to thank you for your cooperation. We regret that your well has been impacted, but remain committed to making sure your water is safe to use and keeping you informed. If you have any questions concerning this letter, please contact Gabriel Moreno-Fergusson, Environmental Program Manager, at (210) 698-5208.

Sincerely,

Jaon Shule Jason D. Shirley Installation Manager

Enclosure

cc: Mr. Greg Lyssy, EPA Region 6
Mr. Kirk Coulter, TCEQ Central Office
Mr. Henry Karnei, TCEQ Region 13
Ms. Kyle Cunningham, San Antonio Metropolitan Health Dist.
Ms. Julie Burdey, Parsons

AFCEE ORGANIC ANALYSES DATA SHEET 2 RESULTS

Analytical Method: EPA 8260B

Preparatory Method: 5030B

AAB #: 110909AS-159130

Matrix: Water

Contract #: 2010*1286022*000

Lab Sample ID: AY45743

Field Sample ID: OFR-3 % Solids: NA

Initial Calibration ID: S110908

Date Received: 07-Sep-11

Lab Name: APPL, Inc

Date Prepared: 09-Sep-11

Date Analyzed: 09-Sep-11

Concentration Units: ug/L

Analyte	MDL	RL	RL Concentra		Dilution	Confirm	Q	ualifier
1,1-DCE	0.12	1.2	0.1		1	1		U
CIS-1,2-DCE	0.07	1.2		0.07	1		1	
TCE	0.05	1.0		5.14	1			
TETRACHLOROETHENE	0.06	1.4		7.72	1			
TRANS-1,2-DCE	0.08	0.6		0.08	1			U
VINYL CHLORIDE	0.08	1.1		0.08]			U
Surrogate		Re	Recovery		Control Limits		ïer	
SURROGATE: 1,2-DICHLOROETHANE-			106		69-1	39		
SURROGATE: 4-BROMOFLUOROBENZ			100		75-125			
SURROGATE: DIBROMOFLUOROM		Ή	106		75-125			I
SURROGATE: TOLUENE-D8 (S)			97.1		75-12			
Internal Std				Qu	alifier			
1,4-DICHLOROBENZENE-D4 (IS)								
CHLOROB	CHLOROBENZENE-D5 (IS)							
FLUOROBENZENE (IS)								

Comments:

ARF: 65592

AFCEE FORM O-2

AFCEE ORGANIC ANALYSES DATA SHEET 2 RESULTS

Analytical Method: EPA 8260B

Preparatory Method: 5030B AAB #: 110909AS-159130

Lab Name: APPL, Inc

Contract #: 2010*1286022*000

)0

Date Analyzed: 09-Sep-11

Matrix: Water

Field Sample ID: OFR-3-A2

Lab Sample ID: AY45744

% Solids: NA

Initial Calibration ID: S110908

Date Prepared: 09-Sep-11

Date Received: 07-Sep-11 Concentration Units: ug/L

MDL Analyte RL Concentration Dilution Confirm Qualifier 1,1-DCE 0.12 1.2 0.12 U 1.2 CIS-1,2-DCE 0.07 0.07 U TCE 0.05 1.0 0.05 U 1 TETRACHLOROETHENE 0.06 U 0.06 1.4 TRANS-1,2-DCE 0.08 0.6 0.08 U VINYL CHLORIDE 0.08 1.1 0.08 U 1 Surrogate Recovery **Control Limits** Qualifier SURROGATE: 1,2-DICHLOROETHANE-101 69-139 SURROGATE: 4-BROMOFLUOROBENZ 101 75-125 SURROGATE: DIBROMOFLUOROMETH 97.4 75-125 SURROGATE: TOLUENE-D8 (S) 97.6 75-125 Internal Std Qualifier 1,4-DICHLOROBENZENE-D4 (IS)

CHLOROBENZENE-D5 (IS) FLUOROBENZENE (IS)

Comments:

ARF: 65592

AFCEE FORM O-2