

DEPARTMENT OF THE ARMY CAMP STANLEY STORAGE ACTIVITY, MCAAP 25800 RALPH FAIR ROAD, BOERNE, TX 78015-4800

August 25, 2014

U-066-14

7850 Smokey View Boerne, TX 78015

SUBJECT: Sampling of Water Well JW-31, Located at 7850 Smokey View

Dear

Camp Stanley Storage Activity (CSSA) collected a groundwater sample from your well (JW-31) on 6/5/14. This sample was submitted to a laboratory contracted by CSSA's environmental contractor for volatile organic compound (VOC) analysis. This letter provides you with the VOC data from the laboratory results and a formal thank you for your assistance in this groundwater monitoring effort.

Based on the analytical data, no VOCs related to CSSA's groundwater investigation were identified in the water sample from your well. Results from the laboratory analysis are provided as an attachment for the above sampling event.

As part of the ongoing CSSA environmental program, we are continuing to investigate and cleanup VOC source areas on the installation and to track these compounds in groundwater on- and off-post. As part of this effort, your well is scheduled to be sampled again in March 2015.

Again, we would like to thank you for your cooperation. We remain committed to making sure your water is safe to use and keeping you informed. If you have any questions concerning this letter, please contact Gabriel Moreno-Fergusson, Environmental Program Manager, at (210) 295-7014.

Sincerely,

Jason D. Shirley Installation Manager

Enclosure

cc:

Mr. Greg Lyssy, EPA Region 6

Mr. Michael Kuitu, TCEQ Central Office

Mr. Jorge Salazar, TCEQ Region 13

Ms. Kyle Cunningham, San Antonio Metropolitan Health Dist.

Ms. Julie Burdey, Parsons

Qualifiers for laboratory data report:

U - The analyte was analyzed for, but not detected. The associated numerical value is at or below the laboratory method detection limit (MDL).

F - Indicates the value is above the laboratory method detection limit (MDL), but below the laboratory reporting limit (RL) for the compound.

Abbreviations:

MDL – method detection limit RL – reporting limit DCE – Dichloroethene TCE – Trichloroethene

AFCEE ORGANIC ANALYSES DATA SHEET 2 RESULTS

Analytical Method: EPA 8260B

Preparatory Method:

AAB #: 140611AM-187398

Lab Name: APPL, Inc

Contract #: *G012

Field Sample ID: JW-31

Lab Sample ID: AY97723

5030B

Matrix: Water

% Solids: NA

Initial Calibration ID: M140605

Date Received: 06-Jun-14

Date Prepared: 11-Jun-14

Date Analyzed: 11-Jun-14

Concentration Units: ug/L

Analyte	MDL	RL	Concentration	Dilution	Confirm	Qualifier
1,1-DCE	0.12	1.2	0.12	1		L
CIS-1,2-DCE	0.07	1.2	0.07	1		ι
TCE	0.05	1.0	0.05	1		L
TETRACHLOROETHENE	0.06	1.4	0.06	1		l
TRANS-1,2-DCE	0.08	0.6	0.08	1		l
VINYL CHLORIDE	0.08	1.1	0.08	1	9	l

Surrogate	Recovery	Control Limits	Qualifier
SURROGATE: 1,2-DICHLOROETHANE-	113	69-139	
SURROGATE: 4-BROMOFLUOROBENZ	104	75-125	
SURROGATE: DIBROMOFLUOROMETH	107	75-125	
SURROGATE: TOLUENE-D8 (S)	102	75-125	

Internal Std	Qualifier
1,4-DICHLOROBENZENE	E-D4 (IS)
CHLOROBENZENE-D5 (I	(S)
FLUOROBENZENE (IS)	

~		0000400	
1 0	mr	ne	nts:
~	4444	110	u.w.

ARF: 73525