

Buddy Garcia, *Chairman*
Larry R. Soward, *Commissioner*
Bryan W. Shaw, Ph.D., *Commissioner*
Glenn Shankle, *Executive Director*



TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

Protecting Texas by Reducing and Preventing Pollution

February 28, 2008

Camp Stanley Storage Activity
25800 Ralph Fair Road
Boerne, TX 78015-4800
Attention: LTC Jason D. Shirley, Installation Manager

Re: Letter dated October 18, 2007 pertaining to Solid Waste Management (SWMU) Unit B-14 and Coal Bin Area - Approval
Camp Stanley Storage Activity (CSSA), Boerne, TX
EPA ID No. TX2210020739
TCEQ Solid Waste Registration No. 69026

Dear LTC Shirley:

The Texas Commission on Environmental Quality (TCEQ) has received the above letter dated October 18, 2007. Your letter enclosed a copy of the original correspondence dated January 10, 2003, addressed to Mr. Kirk Coulter. The 2003 letter states that field investigation of SWMU B-14 did not indicate any spent brass casing at the surface. Historical aerial photographs also do not show any waste management activities at this area. For the coal bin area, field investigation did not indicate any evidence that the site was used for waste disposal or waste management activity. CSSA recommended that these areas do not require further investigation and/or remediation and should be removed from the EPA RCRA 3008(h) Administrative Order list of potential solid waste management units.


The TCEQ concurs with your recommendation – No Further Investigation or remediation is required.

Please be aware that it is the continuing obligation of persons associated with a site to ensure that municipal hazardous waste and industrial solid waste are managed in a manner which does not cause the discharge or imminent threat of discharge of waste into or adjacent to waters in the State, a nuisance, or the endangerment of the public health and welfare as required by 30 TAC §335.4. If the activities described in the report fail to comply with these requirements, CSSA shall take any necessary and authorized action to correct such conditions. A TCEQ field inspector may conduct an inspection of the site to determine compliance with the report.

LTC Jason Shirley
February 28, 2008
SWR 69026
Page 2

Please call me at 512.239.2371 or email me at srayos@tceq.state.tx.us if you need additional information or wish to discuss the content of this letter. When responding by mail, please submit an original and one copy of all correspondence and reports to the TCEQ Remediation Division at Mail Code MC-127. An additional copy should be submitted to the local TCEQ Region Office, in San Antonio.

Sincerely,



Sonny Rayos, P.G., Project Manager
Team 3, Environmental Cleanup II
Remediation Division
Texas Commission on Environmental Quality

SR/sr

cc: Ms. Glare Sanchez, Camp Stanley Storage Activity, 25800 Ralph Fair Rd., Boerne, TX 78015-4800
Mr. Greg Lyssy, U.S. EPA Region 6, 1445 Ross Ave (6SF-LT), Dallas, TX 75202-2733
Ms. Julie Burdey, Parsons Inc., 8000 Centre Park Drive, Suite 200, Austin, TX 78754
Waste Program Manager, TCEQ Region 13 Office, San Antonio, TX