

## TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

Protecting Texas by Reducing and Preventing Pollution

September 09, 2021

## Via E-mail

Mr. T. Glenn Moore Installation Manager Camp Stanley Storage Activity 25800 Ralph Fair Road Boerne, TX 78015

Re: Approval - No Further Action

Response to TCEQ Request for Additional Information on Release Investigation

Report - Area of Concern 78, June 25, 2021 Camp Stanley Storage Activity, Boerne, Texas

TCEQ SWR No. 69026; CN602728206; RN100662840

EPA ID No. TX2210020739

The Texas Commission on Environmental Quality (TCEQ) has reviewed the above-referenced submittal. The report was prepared to clarify the statistical method used in evaluating the release investigation and clean-up at area of concern (AOC) – 78. The statistical test was made using the 95% upper confidence limit per 30 Texas Administrative Code (TAC) §350.79(2)(A). The established 95% upper confidence limit of the mean of 73.1 mg/kg does not exceed the background concentration for lead at the site. *Based on our review of the submittal and other available information, the TCEQ approves the report and No Further Action is required at the site.* 

Please be aware that it is the continuing obligation of persons associated with a site to ensure that municipal hazardous waste and industrial solid waste are managed in a manner which does not cause the discharge or imminent threat of discharge of waste into or adjacent to waters in the state, a nuisance, or the endangerment of the public health and welfare as required by 30 TAC §335.4. If the well plugging and abandonment activities fail to comply with these requirements, please take any necessary and authorized action to correct such conditions.

Questions concerning this letter should be directed to me at (512) 239-6526. When responding by mail, please submit one paper copy and one electronic copy (on USB or disc) of all correspondence and reports to the TCEQ Remediation Division at Mail Code MC-127. An additional copy should be submitted in electronic format to the local TCEQ Region Office. The information in the reference block should be included in all submittals. Note that the electronic and hard copies should be identical, complete copies. A Correspondence ID Form (TCEQ Form 20428) must accompany each document submitted to the Remediation Division and should be affixed to the front of your submittal. The Correspondence ID Form helps ensure that your documents are identified correctly and are routed to the applicable program for a timely response.

Mr. T. Glenn Moore Page 2 September 09, 2021 TCEQ SWR No. 69026

Sincerely,

Timothy Brown, Project Manager

Team 1, VCP-CA Section Remediation Division

Sintly Braine

Texas Commission on Environmental Quality

TKB/\_\_\_

cc: Ms. Julie Burdy, Parsons Inc., 9101 Burnet Road, Suite 210, Austin, TX 78758 (Via E-mail)

Mr. Cameron Lopez, Waste Section Manager, TCEQ Region 13 Office, San Antonio (Via E-mail)