



Photo 33: Broken, abandoned pipe carrying sewage approximately 300 yards downstream of motor pool leach field.



Photo 34: Motor pool service pit which drains to ground.