



Attachment 2

Summary of Solid Waste Management Unit  
and Area of Concern Status Table

Unit No.	Description	Estimated Amount Spent (in \$1,000)	Mapping	Soil-gas	Geophysics		Surface Sampling	Subsurface Investigation	Additional Investigation	Treatability Study	Remediation (Contaminants)	Remediation (UXO/Scrap metal)	Investigation Report(s)	Recommendations	Closure Recommended		Closure Approved by Regulators
					EM	GPR									RRS1	TRRP	
AO 44	Fox holes and trenches. UXO includes Stokes mortars and 20-lb bombs. Located south of B-9 along west slope of hill.	\$0	--	--	--	--	--	--	--	--	--	--	--	--			
AO 45	Flat area with spent and undamaged bullets. Located east of B-31, near bend in road.	\$0	--	--	--	--	--	--	--	--	--	--	--	--			
AO 46	Bermed area with stockpile of lead shot and sand. Located south of Engineering on east side of Thompkins Road.	\$0	--	--	--	--	--	--	--	--	--	--	--	--			
AO 47	Area of trenches and mounds (similar to B-15/16). South of B-15/16, in SW area of East Pasture.	\$73	Aug-99	Aug-96 (see B-15/16)	Aug-99	Aug-99	Jun-00 (SS1-3)	--	--	--	--	--	RFI/Closure Report	RRS1 Closure	X		September-02
AO 48	Three N-S trending mounds and a construction debris pile. Located north of B-15/16.	\$73	--	Aug-96 (see B-15/16)	Jul-Aug-99	Jul-Aug-99	Jun-00 (SS1-3)	--	--	--	--	--	RFI Report Delisting Report	RRS1 Closure	X		
AO 49	Trench (4 x 7 ft) without surficial debris. Located SW of deer stand 41 in central East Pasture.	--	--	--	--	--	--	--	--	--	--	--	--	--			
AO 50	Area with orange discolored material (most likely nickel penetrate) at ground surface. South of B-30 along gravel road.	\$63	--	--	--	--	--	--	Jan-04 (SW01-06, BOT01-03) Feb-04 (BOT04, SW07-08) Mar-04 (BOT05-06) Apr-04 (SW09-13, BOT07)	--	In-Progress	--	RFI Report closure report in progress	RRS1 Closure	X		
AO 51	East pasture, east of active range, approximately 25 acres, area around B-9	--	--	--	--	--	--	--	--	--	--	Feb-97 (UXO clearance)	--	--			
AO 52	Area west of B-4 towards Salado Creek near trees, two trenches	--	--	--	--	--	--	--	--	--	--	--	--	--			
AO 53	Building foundation near B-27 at Central Road and road to "D" Tank, batteries at rear of slab	--	--	--	--	--	--	--	--	--	--	--	--	--			
AO 54	Area near gutting pit, east of Welding Shop Building, right side of road batteries were stored in the area	--	--	--	--	--	--	--	Dec-03 (BOT01, SW01-04) Mar-04 (SW05, BOT02)	--	--	--	--	--			
AO 55	Landfill, south of Tenberg Drive, east of Salado Creek	--	--	Jan-Feb-01	Oct-02	--	Oct-02 (SW1-5, SE1) Feb-03 (SW6-25) Nov-Dec-03 (CL01-14)	--	Oct-02 Feb-03 Nov-03 (CL01-12)	--	--	Feb-03 -	RFI/Closure Report Final Feb 04	Closure	X		
AO 56	Landfill, at intersection of Bernard Road and East Outer Road, surface depression on south side of intersection	\$73	Aug-99	--	Aug-99	Aug-99	Jan-00 (SS1-3)	--	Feb-04 (SW01-06, BOT01-02)	--	--	--	Closure Report June 04	RRS1 Closure	X		
AO 57	East of Building 98 and KOA Area, cleaning/maintenance activities performed at temporary structures	--	--	Jan-Feb-01	--	--	--	--	--	--	--	--	--	--			
AO 58	Suspected disposal trench within Inner Cantonment	\$73	Aug-99	--	Aug-99	Aug-99	Jan-00 (SS1-3)	--	--	--	--	--	RFI Report	Investigate anomaly			
AO 59	Trench-type anomaly located west Test Pad in the East Pasture	--	--	--	--	--	--	--	--	--	--	--	--	--			
AO 60	Trench located west of tunnel and entrance roadway in the East Pasture.	--	--	--	--	--	--	--	--	--	--	--	--	--			
AO 61	Suspected landfill	\$73	Aug-99	--	Aug-99	Aug-99	Jan-00 (SS1-3)	--	--	--	--	--	RFI/Closure Report	RRS1 Closure	X		February-03
AO 62	Located west of monitoring well MW-2 and east of Salado Creek.	--	--	--	--	--	--	--	--	--	--	--	--	--			
AO 63	Area consisting of 3 barrels containing rocks, south of deer stand 41 in the East Pasture.	--	--	--	--	--	--	--	--	--	--	--	--	--			
AO 64	Area east of SWMU B-4; flares observed in the area	--	--	--	--	--	--	--	--	--	--	--	--	--			
AO 65	A concrete pit area that housed a metal vat that contained TCE and PCE.	\$201	Mar-00	Jan-Feb-01	--	--	--	Mar-00 (SB1); Mar-Apr-01 (SB2-13, MW1-4)	--	--	--	--	RFI Report Closure Report June 04	(further characterization of COC plumes) RRS1 Closure	X		
AO 66	Area north of Well 16 in the outer cantonment.	\$44	Dec-99	Dec-99	--	--	--	--	--	--	--	--	--	--			
AO 67	Concrete pad near Building 90 housed a vat containing cleaning solvents.	\$110	Apr-01	Jan-Feb-01	--	--	--	Apr-01 (SB1-3)	Mar-04 (SW01-04, BOT01) Apr-04 (SW05-07) May-04	--	In-Progress	In-Progress	RFI Report	--			
AO 68	Area includes metal slag/debris storage area from Wheelabrator operations next to Building 90-2.	--	--	--	--	--	--	--	--	--	--	--	--	--			
AO 69	Located on west side of CSSA.	--	--	--	--	--	--	--	--	--	--	--	--	--			(Not available)
AO 70	Building used to mix pesticides. Near Building 1.	--	--	--	--	--	--	--	--	--	--	--	--	--			(Not available)
AO 72	Area containing concrete, possible asbestos. Located east of Building 94, in SW CSSA.	--	--	--	--	--	--	--	--	--	--	--	--	--			(Not available)
AO 73	Ranch landfill with overgrown trenches. Near Well 11, in northwest corner of CSSA.	--	--	--	--	--	--	--	--	--	--	Trash removed by CSSA personnel: barbed wire, rusted razor blades, broken glass.	--	--			(Not available)