



Excavated soils from Liner Investigation, Jan., 96. Photograph by K. Caske  
Parsons ES



Electrokinetic well boring, July 97. Photograph by Lynntech, Inc.



Electrokinetic Well Casing Installation, July 97. Photograph by Lynntech, Inc.



Electrokinetic Well "Coarse and packing installation", July 97.  
Photograph by Lynntech, Inc.




Electrokinetic well fine sand packing installation, July 97.  
Photograph by Lynntech, Inc.




Electrokinetic Well without process controller installed. July 97  
Photograph by Lynntech, Inc.



Electrokinetic field pilot scale layout, July 97.  
Photograph by Lynntech, Inc.



Electrokinetic cathode well process controller, July 97.  
Photograph by Lynntech, Inc.



Trench excavation showing cross-section from final performance testing. Jan 98.  
Photograph by Parsons ES.



Trench excavation from field performance testing, Jan. 98.  
Photograph by Parsons ES.